



Hubbell Building Automation
Low Voltage Sensors (devices)
Requires 33mA each

NOTE:

1. DO NOT attempt to power more than 4 devices, be it sensors or slave packs, from a single power pack.

1 circuit with up to 4 sensors and UVPP



Building Automation, Inc.